

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-010926**Date Inspected:** 02-Jan-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Li Yang**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Segment**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, M.Manikandan was present during the time noted above for observations relative to the work being performed.

OBG # TRIAL ASSEMBLY YARD

This QA inspector measured and recorded root gap and offset for below segment along with QA inspector (Mr. Manjunath). Reports forwarded to team leader for further action.

6BW-6CW

This QA Inspector randomly observed the following work in progress:

OBG # TRIAL ASSEMBLY YARD (6AE-6BE)

ZPMC performed flame cutting and removed welds of 6AE and 6BE transverse splice weld located on side panel Bike path side. ZPMC CWI is identified as Li Yang. Cutting was been performed against welding repair report B-WR9154 Rev.0.

OBG # TRIAL ASSEMBLY YARD (6BW-6CW)

FCAW Process:

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Welding of weld joint – 003 located on PCMK OBW6C, bottom panel. Welder is identified as 220066. ZPMC CWI is identified as Li Yang. The welding variables recorded by QC appeared to comply with the WPS-B-T-2231T-1.

FCAW Process:

Welding of weld joint – 003 located on PCMK OBW6C, bottom panel. Welder is identified as 053609. ZPMC CWI is identified as Li Yang. The welding variables recorded by QC appeared to comply with the WPS-B-T-2231T-1.

FCAW Process:

Welding of weld joint – 003 located on PCMK OBW6C, bottom panel. Welder is identified as 200676. ZPMC CWI is identified as Li Yang. The welding variables recorded by QC appeared to comply with the WPS-B-T-2231T-1.

Welding was been performed against welding repair report B-WR9652 Rev.0 for excess root gap.

OBG # TRIAL ASSEMBLY YARD (5CE)

SMAW Process:

Welding of weld joint – 008 located on PCMK SEG026A, longitudinal weld joining side and bottom panel. Welder is identified as 054467. ZPMC CWI is identified as Li Yang. Welding was been performed against ABF-RFI-001938R01. The welding variables recorded by QC appeared to comply with the WPS-345-SMAW-4G (4F)-FCM-Repair-1.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No Relevant Conversation.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact , who represents the Office of Structural Materials for your project.

Inspected By:	Manikandan,Murugan
----------------------	--------------------

Quality Assurance Inspector

Reviewed By:	Miller,Mark
---------------------	-------------

QA Reviewer
